

Metal Roof



Common Roofing Issues



Fasteners backing out and dirt and debris buildup



Rust



Failing fastener grommet



Horizontal seams separating

ASTEC Solution



Tighten/replace fasteners and pressure wash and clean



Treat rust to prevent further rust formation



Encapsulate and waterproof fasteners



Fully reinforce horizontal seams

Metal Roof



Common Roofing Issues

ASTEC Solution



Vertical seams separating



Fully reinforce vertical seams



Failing penetrations



Seal and waterproof penetrations




Loose or missing foam inserts



Foam, trim, seal and waterproof open voids



Deteriorating skylights



Rejuvenate fiberglass skylights

Metal Roof



Problem Roof—Before

ASTEC Roof—After



Entire roof receives multiple coats of ASTEC Finish



Seamless monolithic system



Attention to detail



10 or 15-year renewable product and labor warranty